Reliability Standards FAC-003-1 and FAC-008-1

- Why do we have them?
- What do they mean and how do they affect you?
- How can PLS-CADD help you?

Presented by

Alan DeJong, PE

Kevin Brzys, PE

Reason:

- 1. Vegetation caused outage and subsequent blackout of 2003
 - Facts
 - Blackout affect over 50 million people
 - 265 power plants shut down
 - Ambient temp of 88°F
 - Canada blamed US, US blamed Canada

2003 Blackout:

- Causes
 - Many examples of human failure
 - Main cause was the failure to trim trees on a rural line in Ohio.
 - (4) 345 kV lines fail due to direct contact with trees during maximum thermal conditions.

Solution:

- Energy Policy Act of 2005
 - Granted the Federal Energy Regulatory
 Commission (FERC) the right to review and approve mandatory reliability standards for the nations bulk transmission system.
 - Authorized FERC to certify a National Electric Reliability Organization (ERO) to develop and enforce mandatory reliability standards for the bulk-power system.

Solution:

- Energy Policy Act of 2005
 - FERC designated the North American Electric Reliability Corporation (NERC) as the Electric Reliability Organization (ERO)
 - NERC creates these standards with cooperation and input from industry and other stakeholders.
 - NERC, in turn, designated eight Regional Entities, which also operate under FERC authority, to address and implement standards at a regional level.

Purpose:

to improve the reliability of the transmission grid by:

- Preventing outages from vegetation on rights of way
- Minimizing outages from vegetation adjacent to rights of way
- Maintaining clearances between lines and vegetation
- Reporting vegetation related outages

Requirements:

- 1. The transmission owner shall prepare and keep current a transmission vegetation management plan (TVMP)
 - The TVMP shall define a schedule for R/W inspections
 - The TVMP shall identify and document vegetation clearances at maximum design loading, and with the effects of wind (not defined)
 - Specifically, maintenance clearances (clearance 1)
 and flashover clearances (clearance 2)

Requirements:

- 2. The transmission owner shall create a work plan for vegetation management.
- 3. The transmission owner shall report quarterly to its RRO any sustained outages.
 - Category 1 = Grow-ins from inside the R/W
 - Category 2 = Fall-ins from inside the R/W
 - Category 3 = Fall-ins from outside the R/W

Measurements:

- 1. The transmission owner has a documented TVMP.
- 2. The transmission owner has a documented work plan.
- 3. The transmission owner has supplied the outage reports to it's RRO.
- 4. The RRO has supplied the outage reports to NERC.

Compliance:

- 1. Monitoring.
- 2. Levels of non-compliance.
 - Level 1 Incomplete TVMP or work plan or an outage report wasn't correctly submitted.
 - Level 2 1 category 2 outage in a calendar year.
 - Level 3 1 category 1 outage or multiple category 2 outages.
 - Level 4 Multiple category 1 outages in a calendar year.

FAC-008-1 Facility Ratings Methodology

The purpose is to ensure that facility ratings are determined based on an established methodology:

Requirements:

- 1. The rating methodology shall be documented.
- 2. The rating methodology shall be open for inspection and technical review.
- 3. The transmission owner shall respond to questions in regard to it's rating methodology in 45 days.